



**Note:**

If you use "," (comma) instead of "." (dot) as the decimal separator on your computer, the JAC software does not work appropriately. Please follow the procedure below.


1. Click on [Date, Time, Language, and Regional Options] in Control panel.



2. Click on [Regional and Language Options].



3. Select [Regional Options] tab and click on [Customize...] button.



4. Set [Decimal symbol] to "." (dot) and [Digit grouping symbol] to "," (comma).

